

**To:** Kevin Shaver (kshaver@gesoncall.com)[kshaver@gesoncall.com];  
djohnson@gesoncall.com[djohnson@gesoncall.com]; Richard Cole  
(rcole@gesoncall.com)[rcole@gesoncall.com]  
**From:** Daly, Eric  
**Sent:** Fri 5/13/2016 12:19:43 PM  
**Subject:** HTC-5374 Roberts Street  
5374 Roberts Street Building Footprint.pdf

Good Morning:

Below are the answers to the radon system installer. I have attached a basic footprint map of the basement. However, Peter will be providing us a map with measurements shortly.

- [ ] Basement is all concrete
- [ ] Sump is concrete with drain tile in floor draining to sump area
- [ ] Basement has been dry
- [ ] There is no gaps between basement flooring and upright walls
- [ ] There are a few settlement cracks that exists in floor and walls
- [ ] No Radiant heat in flooring in basement
- [ ] The new addition/family room is built on a surrounding footer on 2x12 floor joists

Regards,

Eric

"We must, indeed, all hang together, or assuredly we shall all hang separately", Benjamin Franklin

Eric M. Daly

On-Scene Coordinator/Radiological Response Specialist

US Environmental Protection Agency- Region II

ERRD/RPB/PPS

2890 Woodbridge Avenue

Edison, NJ 08837

[daly.eric@epa.gov](mailto:daly.eric@epa.gov)

732-321-4350